

1600 Shore Road • Naperville, Illinois 60563 • Phone (630) 778-1200 • Fax (630) 778-1233

August 13, 2007

Ms. Lisa Graczyk **DYNAMAC CORPORATION**WESTON SOLUTIONS, INC.
20 N. Wacker Drive Suite 1210
Chicago, IL 60606-2901

Project ID: 05-PC-08/10/07-006 First Environmental File ID: 7-3574 Date Received: August 10, 2007

Dear Ms. Lisa Graczyk:

The above referenced project was analyzed as directed on the enclosed chain of custody record.

All Quality Control criteria as outlined in the methods and current IL ELAP/NELAP have been met unless otherwise noted. QA/QC documentation and raw data will remain on file for future reference. Our accreditation number is 100292 and our current certificate is number 001767: effective 06/11/07 through 02/28/08.

I thank you for the opportunity to be of service to you and look forward to working with you again in the future. Should you have any questions regarding any of the enclosed analytical data or need additional information, please contact me at (630) 778-1200.

Sincerely,

Lorrie Franklin Project Manager

IL ELAP / NELAC Accreditation # 100292

1600 Shore Road • Naperville, Illinois 60563 • Phone (630) 778-1200 • Fax (630) 778-1233

Case Narrative

DYNAMAC CORPORATION

Project ID: 05-PC-08/10/07-006
First Environmental File ID: 7-3574
Date Received: August 10, 2007

Flag	Description	Flag	Description
<	Analyte not detected at or above the reporting limit.	L+	LCS recovery outside control limits; high bias.
В	Analyte detected in associated method blank.	. L-	LCS recovery outside control limits; low bias.
. C	Identification confirmed by GC/MS.	M	MS recovery outside control limits; LCS acceptable.
D	Surrogates diluted out; recovery not available.	M+	MS recovery outside control limits high bias; LCS acceptable.
E	Estimated result; concentration exceeds calibration range.	M-	MS recovery outside control limits low bias; LCS acceptable.
F	Field measurement.	N	Analyte is not part of our NELAC accreditation.
		ND	Analyte was not detected using a library search routine; No calibration standard was analyzed.
G	Surrogate recovery outside control limits; matrix effect.	P	Chemical preservation pH adjusted in lab.
Н	Analysis or extraction holding time exceeded.	Q	The analyte was determined by a GC/MS database search.
J	Estimated result; concentration is less than calib range.	S	Analyte was sub-contracted to another laboratory for analysis.
K	RPD outside control limits.	Т	Sample temperature upon receipt exceeded 0-6°C
RL	Routine Reporting Limit (Lowest amount that can be detected when routine weights/volumes are used without dilution.)	W	Reporting limit elevated due to sample matrix.

All quality control criteria, as outlined in the methods, have been met except as noted below or on the following analytical report.

Sample Batch Comments:

Sample acceptance criteria were met.

IL ELAP / NELAC Accreditation # 100292

1600 Shore Road • Naperville, Illinois 60563 • Phone (630) 778-1200 • Fax (630) 778-1233

Analytical Report

Client: DYNAMAC CORPORATION

Project ID: 05-PC-08/10/07-006 **Sample ID:** PC-S-01-081007

Sample ID: PC-S-01-081007 **Sample No:** 7-3574-001

Anaryticai Kepurt

Date Collected: 08/10/07

Time Collected: 8:15 **Date Received:** 08/10/07

Date Reported: 08/13/07

Results are reported on a dry weight basis

Results are reported on a dry weight basis		· · · · · · · · · · · · · · · · · · ·					
Analyte		Result	R.L.	Units	Flags		
Solids, Total Analysis Date: 08/10/07	Method: 160.3						
Total Solids		75.65		%			
BTEX Organic Compounds Analysis Date: 08/11/07	Method: 5035A/	/8260B					
Benzene		< 2.0	2.0	ug/kg			
Ethylbenzene		< 5.0	5.0	ug/kg			
Toluene		< 5.0	5.0	ug/kg			
Xylene, Total		< 5.0	5.0	ug/kg			
Polynuclear Aromatic Hydrocarbons Analysis Date: 08/13/07	Method: 8270C		Preparation Method 3540C Preparation Date: 08/12/07				
Acenaphthene		< 50	50	ug/kg			
Acenaphthylene		< 50	50	ug/kg			
Anthracene		< 50	50	ug/kg			
Benzo(a)anthracene		< 8.7	8.7	ug/kg			
Benzo(a)pyrene		< 15	15	ug/kg			
Benzo(b)fluoranthene		< 11	11	ug/kg			
Benzo(k)fluoranthene		< 11	11	ug/kg			
Benzo(ghi)perylene		< 50	50	ug/kg			
Carbazole		< 330	330	ug/kg			
Chrysene		< 50	50	ug/kg			
Dibenzo(a,h)anthracene		< 20	20	ug/kg			
Fluoranthene		< 50	50	ug/kg			
Fluorene		< 50	50	ug/kg			
Indeno(1,2,3-cd)pyrene		< 29	29	ug/kg			
2-Methylnaphthalene		< 50	50	ug/kg			
Naphthalene		< 25	25	ug/kg			
Phenanthrene		< 50	50	ug/kg			
Pyrene		< 50	50	ug/kg			

US EPA Emergency Response Branch

START III, Chicago, IL

EPA Contract Number: EP-S5-06-04

CHAIN OF CUSTODY RECORD

Site #: 05-PC

Contact Name: Lisa Graczyk
Contact Phone: 312-305-6745

No: 05-PC-08/10/07-0006

Cooler #: 1

Lab: First Environmental Lab Phone: 630-778-1200

Lab#	Sample #	Location	Sub Location	Analyses	Matrix	Collected	Num b Cont		Preservati ve	Coll Method	Sample Time	D e p t	p t h U n
	05-PC-0015 PC-S-01- 081007	Area 128	Bottom	ВТЕХ	Soil	8/10/2007	1	40oz vial	Methanol	Grab	08:15	1 0	1 1
	PC-S-01- 081007	Area 128	Bottom	BTEX	Soil	8/10/2007	2	40oz vial	Na2SO4	Grab	08:15	1 0	1 - 1
	PC-S-01- 081007	Area 128	Bottom	PAH, 2-methylnaphthalene, carbazole	Soil	8/10/2007	1	Jar	4 C	Composit e	08:15	1 0	f

Special Instructions: 24 Hr TAT. Sampler: M Bondie

CHAIN OF CUSTODY #

Items/Reason	Relinquished by	Date	Received by	Date	Time	Items/Reason	Relinquished By	Date	Received by	Date	Time
ProKup	200	870-0-	Ah	Elde	1130						
J 6 6 0 0	-001-9-0		X	11901							